# Oil Field Environmental Incident Summary

**Responsible Party:** SLAWSON EXPLORATION COMPANY, INC. **Well Operator:** SLAWSON EXPLORATION COMPANY, INC.

Well Name: WOLVERINE FEDERAL 5-31-30TFH

Field Name: ELM TREE Well File #: 23108

Date Incident:7/31/2015Time Incident:11:35Facility ID Number:County:MCKENZIETwp: 153Rng: 93Sec: 31Qtr:

**Location Description:** 

Submitted By: Ray Gorka Received By:

Contact Person: Ray Gorka

**1675 BROADWAY STE 1600** 

DENVER, CO 80202

General Land Use: Badlands Terrain

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1.3 MileDistance Nearest Water Well:1.3 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 30 Gallons 28 Gallons

Brine Other

Description of Other Released Contaminant:

.....

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none....

Areal Extent:

On the pad, outside of the berm by 8' X 2'...

# Potential Environmental Impacts:

Minimal....

# Action Taken or Planned:

Tank was emptied, pumper told to keep up with sales oil. Cleanup is progressing today and tomorrow.

Wastes Disposal Location: Licensed disposal facility.

Agencies Involved:

# **Updates**

Date: 8/3/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.